



SUCCESSFUL FAMILY RUN BUSINESS ASSETS FOR SALE TEXOMA WEB GAINESVILLE, TX




Overview:

- Production ends November 1, 2022
- Two (2) 22-3/4" SSC Presses. Purchased new from GOSS, USA Built
- 480v 3ph 60 hz

Equipment:

1. **2000 USA Built 22-3/4" SSC Tower Press** T-bar, OTN, Brush, QTI RMS, 2-150 HP, 2-100 HP, Motorized Comps, Central grease, Pneumatics
 - a. 6-Towers, 3-Tandem 1-Single Enkel splicers 1040-45SE, Enkel 2-Infeeds with web aligners, 1-Infeed no aligner
 - b. 2-Vertical 11' TEC dryers Job NO.16544-86 Model 1VC1.12.40
 - c. 1-Magnum folder (MSC7001), 2-sets nips, cross perf, Double parallel, and quarter folder, air former board
 - d. 1-SSC Folder (859) 1-set of nips, cross perf, air former board, quarter folder, air former and Ribbon deck

COMPLETE PRESS OR RECONFIGURE TO SUITE



QUALITY YOU EXPECT * CUSTOMER SERVICE YOU DESERVE


World Headquarters
11369 Higgins Airport Way, Burlington, WA USA 98233
888.346.6119 www.impressionsworldwide.com
www.impressionsworldwide.com

SE USA Service Facility
202 Enterprise Drive, Tupelo, MS 38804
888.346.6119



2. **1990 USA Built 22-3/4" SSC Book Press** T-bar, OTN, Sock, 1-125 HP, 1-100 HP, Manual Comps, Central grease, Pneumatics
 - a. 4-Two High's, 4-Mono's, 2-Tandem Martin EC1038-4087-1, Fincor 3120 drives,
 - b. SSC 639 1-Set Nips, Cross Perf, and Double Parallel, air former, Ribbon deck
 - c. SSC 640 2-Sets of Nips, and Quarter fold, air former

COMPLETE PRESS OR RECONFIGURE TO SUITE



3. **Muller Martini 227 Inserter**
 - a. 7 into 1
 - b. updated electronics, house air,
 - c. RIMA RS12 SN: 20527
4. **Two (2) Kodak Thermal Platesetter News70**
 - a. 2005 SN NM445 hours on laser: 2565
 - b. 2009 SN NG0580 hours on laser: 1783
 - c. Prinergy 5 server
5. **Two (2) (2018) Glunz and Jensen Thermal Plate Processors**
 - a. MP68
 - b. SN 92903-0207 and 92903-0718
6. **NELA (2005) Automatic Plate Bender (non-optical)**
 - a. 22-3/4" On the Nose SSC profile
 - b. BMK-13939-01
 - c. All air hoses replaced 2021
 - d. NELA plate conveyor from two (2) CTP devices
 - e. NELA plate stacker
7. **1998 McCain S2000 Saddle Stitcher, purchased new**
 - a. 6-Feeders and 1-Cover Feeder, house air
 - b. RIMA RS10S 9-1/4"

QUALITY YOU EXPECT * CUSTOMER SERVICE YOU DESERVE

World Headquarters
11369 Higgins Airport Way, Burlington, WA USA 98233
888.346.6119 www.impressionsworldwide.com
www.impressionsworldwide.com

SE USA Service Facility
202 Enterprise Drive, Tupelo, MS 38804
888.346.6119



8. Two (2) older McCain Saddle Stitchers
9. Two (2) Gammerler KL503/1 stackers with low infeed
10. Four (4) Count-O-Veyors without lasers, or operator touch screen
11. Two (2) Gammerler RS134 3-knife inline trimmers
12. Offline/ not under power covered in plastic
 - a. Muller Martini Inserter 5 into 1
 - i. Missing mail table, no stacker, no air compressor
 - b. Two (2) Kansas Inserters
 - i. 5 into 1 and 3 into 1, no stacker, no compressor
13. Two (2) Offline bundle strappers
14. Buskro mail table with five-line ink jet
15. Kirk-Rudy Taber model 535-CS
16. Roll Rewinder with Gantry
17. Three (3) HP plotters designjet 1050c plus
18. Parts room with handful of tools
19. TriService chiller
20. Thermal oxidizer located outside
21. Komatsu triple Clamp truck, 4480 lb., propane
22. Komatsu triple Fork truck, 2025 lb., propane
23. Balemaster (Balewel) indoor compactor
24. Lake Baler indoor compactor
25. Compactor for corrugated, indoor
26. Baumfolder folder model 18x25 Pile
27. Challenge paper cutter Model GPB Size 370 SN 29981
28. Challenge Diamond paper cutter Size 265
29. SITA pallet wrapper

REMOVAL, INSTALLATION, COMMISSIONING AND TRAINING AVAILABLE ON REQUEST

QUALITY YOU EXPECT * CUSTOMER SERVICE YOU DESERVE

World Headquarters
11369 Higgins Airport Way, Burlington, WA USA 98233
888.346.6119 www.impressionsworldwide.com
www.impressionsworldwide.com

SE USA Service Facility
202 Enterprise Drive, Tupelo, MS 38804
888.346.6119